

RH 7/29/14

LCID State of North Carolina Department of Environment and Natural Resources Division of Waste Management	LAND CLEARING & INERT DEBRIS LANDFILL Facility Annual Report For the period of July 1, 2013-June 30, 2014
--	--

According to (G.S. 130A-309.09D(b)) completed forms must be returned by August 1, 2014 and a copy of this report must be sent to the County Manager of each county from which waste was received. If you have questions or require assistance in completing this report, contact your Regional Environmental Senior Specialist.

RECEIVED
 JUL 22 2014
 SOLID WASTE SECTION

Facility Name: Blaylock Grading Co. Permit: 43C

Physical Address	Mailing Address
Street 1: <u>1025 Claude White Rd.</u>	Street 1: <u>3320 Harnett Central Rd</u>
Street 2: _____	Street 2: _____
City: <u>SANFORD</u> County: <u>Harnett</u>	City: <u>Angier</u>
State: North Carolina Zip: <u>27330</u>	State: North Carolina Zip: <u>27501</u>

Primary Facility Contact Person	Billing Contact Person
Name: <u>Harold G. Blaylock</u>	Name: <u>Harold G. Blaylock</u>
Phone: <u>910 818 8398</u> Fax: <u>910 814 0039</u>	Phone: <u>910 818 8398</u> Fax: <u>910 814 0039</u>
Email: _____	Email: <u>rsblaylock@yahoo.com</u>

1. Tipping Fee: \$ 40.00 per single axle
 Tipping Fee: \$ 45.00 per tandem
 Tipping Fee: \$ 50.00 per triaxle

2. Estimate the amount of waste taken in an average week at this facility? 120 ☐ tons
☒ cubic yards

3. How many weeks did you operate this year? 48

4. What are the hours/days of operation for this facility? 8:00 am - 4:00 pm

5. What is the acreage of the footprint of the waste on site as of June 30? 27 Acre(s)

6. Did your facility stop receiving waste during this past Fiscal Year? ☐ Yes ☒ No
 If so, please report the date this occurred: _____

REMINDER: According to (G.S. 130A-309.09D(b)), this report must be sent to the Regional Environmental Senior Specialist for your area and a copy of this report must be sent to the County Manager of each county from which waste was received.

Please return your completed report to:

CERTIFICATION: I certify that the information provided is an accurate representation of the activity at this facility.

Signature: Harold G. Blaylock Date: 7-15-2014

Name: Harold G. Blaylock Title: Partner

Phone Number: 910 818 8398 Email: rsblaylock@yahoo.com

Facility Name: Blaylock Grading Company Permit: 43C
 Address: 1025 Claude White Rd
 City: Sanford State: North Carolina Zip: 27330
 Person completing Assessment: Cindy Blaylock Date: _____
 Phone Number: 910 893 8653 Fax: _____ Email: blaylockcj@gmail.com

Instructions:

Please indicate either *Yes* or *No* for each Receptor and Post Closure Maintenance question. Then please determine the distance or distances for each Receptor from the *Edge of Waste* (using range finders and/or GIS maps) and type that information into the form. Please attach additional information including GIS maps, lists of potable well locations, etc.

Receptors

1. Are there Residential Dwellings Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No
 If Yes, how many? 16
 What are the three closest distances from the *Edge of Waste*? 250 Feet 250 Feet 250 Feet
2. Are there Potable Wells Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No
 If Yes, how many? _____
 What are the three closest distances from the *Edge of Waste*? _____ Feet _____ Feet _____ Feet
3. Are there Community/Municipal Wells Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No
 If Yes, how many? _____
 What are the three closest distances from the *Edge of Waste*? _____ Feet _____ Feet _____ Feet
4. Are there Surface Water Bodies Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No
 If Yes, how many? _____
 What are the three closest distances from the *Edge of Waste*? _____ Feet _____ Feet _____ Feet
 Please list the names of the water bodies: _____
5. Is Public Water Available Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No
 If Yes, how many of the Residential Dwellings noted above are connected? ALL

Corrective Measures

6. Is there an active methane extraction system (blower, flare, etc.)? ☐ Yes ☒ No
7. Is there a passive methane extraction system (trench, vents in cap, flare, etc.)? ☐ Yes ☒ No
8. Is there groundwater remediation taking place on site? ☐ Yes ☒ No
 If Yes, what is the specific remedial technology used? _____

Comments